



BPOV Support Guide: Importing Files in Trimble Field Link

1. Go to "More"
2. Click "Jobs"



3. Click "Import"



Pittsburgh Office

1120 Ohioview Avenue | Ambridge, PA 15003 | Ph: 724-266-1600 | Fax: 724-266-8161

Columbus Office

372 Morrison Road, Ste. D | Columbus, OH 43213 | Ph: 614-759-1000 | Fax: 614-759-7059

4. Select "Desktop," "Cloud," or "USB"
5. Click "Import"

***Important* Make sure to create job before importing any data**



Pittsburgh Office

1120 Ohioview Avenue | Ambridge, PA 15003 | Ph: 724-266-1600 | Fax: 724-266-8161

Columbus Office

372 Morrison Road, Ste. D | Columbus, OH 43213 | Ph: 614-759-1000 | Fax: 614-759-7059